


Refilling with the TareWeight function

Go to 'Device Maintain' (A), select the pump unit you want to refill (B) and click the 'Refill' button (C). The Iru Mix will fetch the unit and bring it to the turntable.

1



SANTINT Maintenance

Unit ID	Current Amount	Set Amount
WB04	1329,315/1750	
WB2045	1351,47/1750	
WB2030	1360,809/1750	
WB1031	910,28/1050	
WB1030	946,083/1050	
WB1041	926,051/1050	
WB20	941,455/1050	
WB03	361,461/600	
WB1007	397,094/600	
WB1078	414,375/600	
WB1011	397,47/600	
WB1096	413,557/600	
WB1006	397,47/600	
WB06	1310,792/1750	
WB2040	1351,47/1750	
WB2030	1360,809/1750	
WB1003	913,738/1050	
WB1039	937,784/1050	
WB1020	910,28/1050	
WB1005	912,872/1050	
WB85	415,608/600	
WB28	390,796/600	
WB90	386,469/600	
WB67	387,543/600	
WB69	409,514/600	
WB1023	395,593/600	
WB06	1256,733/1750	
WB2040	1351,47/1750	
WB01	839,014/1750	
WB1037	922,499/1050	
WB1033	920,733/1050	
WB1012	912,872/1050	
WB68	921,616/1050	
WB21	397,094/600	
WB1014	397,094/600	
WB45	399,365/600	
WB54	406,337/600	
WB32	374,047/600	
WB42	381,195/600	
WB1035	1300,472/1750	
WB1050	1321,668/1750	
WB2043	0/1767,5	
WB23	920,733/1050	
WB1002	913,738/1050	
WB1004	912,006/1050	
WB61	937,784/1050	
WB26	416,021/600	
WB62	401,662/600	
WB1024	395,22/600	
WB1013	396,717/600	
WB33	401,277/600	
WB53	365,242/600	
WB1032	1302,93/1750	
WB2010	228,824/1750	
WB1001	913,738/1050	
WB1097	929,63/1050	
WB02	907,705/1050	
WB1098	945,154/1050	
WB2060	962,167/1050	
WB07	416,435/600	
WB82	373,841/600	
WB9908	415,608/600	
WB91	383,991/600	
WB30	393,364/600	
WB31	415,197/600	
WB2020	1370,278/1750	
WB2010	923,099/1750	
WB60	120/1050	
WB1009	913,738/1050	
WB64	935,05/1050	
WB63	919,853/1050	
WB1738	415,197/600	
WB25	403,986/600	
WB1021	395,967/600	
WB1779	414,375/600	
WB84	373,114/600	
WB24	392,259/600	
WB1008	396,717/600	

AC60
180619AC100001

Refill Toner

Canister ID	Toner Code	Toner Name	Current Amount	Set Amount
16	WB2043	CROMAX PRO B...	0/1767,5	

Warning Level 181,8 Min Amount 121,2 Unit g

☐ Refill Amount ☒ Set Amount

Refill

2

Refill the pump unit and place it on a scale, note down the weight of the unit. Place it back on the turntable and close the door. The Iru Mix will return it to it's assigned position.

A prompt will appear in AutoPaint, enter the weight of the pump unit (D) and press the 'Refill' button (E). The software will deduct the weight of the pump automatically.

3

Refill Toner

Canister ID	Toner Code	Toner Name	Current Amount	Set Amount
16	WB2043	CROMAX PRO B...	0/1767,5	

Warning Level 181,8 Min Amount 121,2 Unit g

☐ Refill Amount ☒ Set Amount

Refill